

# Peplink Switch Firmware 1.0.1 Release Notes

Release Date: 10/25/2016

## Feature Improvements

Reference no.	Description
15114	<b>Temperature Management:</b> Improved the fan speed control algorithm and temperature reporting.
15257 15260	<b>Web UI:</b> Added help text to various sections of the UI.

## Resolved Issues

Reference no.	Description
15305	<b>Device Management:</b> Unable to access the Web Admin using the management port.
15424	<b>VLAN Management:</b> If the dedicated management VLAN has been specified, and if the total number of VLAN networks is over 32, clients will be unable to acquire an IP address from the Management VLAN.

## Report a Bug

To report a bug, please open a forum thread at <https://forum.peplink.com/>