

AP One Firmware 3.7.3 Release Notes

Release Date: Nov 27, 2020

Devices Supported

- AP One AC Mini HW2
- AP One Flex HW4

New Features

Reference	Description
21477	Added support for Wi-Fi Mesh.
22149	Added the ability to select the minimum Data Rate under SSID Settings.
23189	Added WDS support. (Not compatible with firmware 3.5.x or below)
23294	Added ability to change from "AP Mode" to "Wi-Fi Air Monitoring mode", and the report can be viewed from InControl 2 > Reports > AirProbe Reports.
23073	Added DPI Support.

Improvements

Reference	Description
15936	Added the ability to block specific Wi-Fi clients from the Client List.
22960	The Web UI now uses the "Device Name" instead of the "Router Name" on the Status and System.
23380	Increase the chance for 5GHz Wi-Fi client to use 5GHz channel after Apply Changes.

Resolved Issues

Reference	Description
22201	Fixed an issue on the AP One Flex HW4 where the Client Bandwidth Management feature under SSID may not work.
22369	Fixed an issue where the Captive Portal splash page does not show.
22396	Fixed the issue where the AP One Flex HW4 shows the incorrect LED status.
23370	Fixed an issue where the transmit power is low when the unit boots up.

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>