

AP Firmware 3.9.1 Release Notes

Release Date: Mar 21, 2022

Important Notes

- This firmware adjusts the Tx power levels for the AP One AX / AX Lite when used in EU regulatory environments (reference #26642). Using the Power Boost feature will exceed local regulatory limits.

Devices Supported

- AP One AX
- AP One AX Lite
- AP One AC Mini HW2
- AP One Flex HW4

New Features

Reference	Description
26956	WPA3 Enterprise encryption

Improvements

Reference	Description
26642	AP One AX / AX Lite: adjust the TX power level according to EU regulations
26291	Added: Operating Country - Argentina
25567	Added: SNMP supports OWE Security
25402	Added: SNMP supports Wi-Fi retries and error count

Resolved Issues

Reference	Description
27285	Fixed: In Beta 1, Client Signal Strength Threshold might cause clients to not connect
25453	Fixed: 802.11a/b/g modes did not work on AP One AX
25484	Fixed: Mesh might reconnect occasionally
25408	Fixed: Wi-Fi FragAttack Vulnerability

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>