

AP One Firmware 3.9.2 build 4892

Release Notes

Release Date: Aug 31, 2022

Devices Supported

- AP One AX
- AP One AX Lite
- AP One Rugged HW2

Resolved Issues

Reference	Description
28473	Fixed: Firmware upgrade might not succeed on AP One AX/Lite
28335	Fixed: Incorrect MAC address suffix assignment that found on firmware 3.9.2 build 4891

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>