

# AP One Firmware 3.9.3 Release Notes

Release Date: Sep 21, 2023

## Devices Supported

This firmware release supports the following devices:

- AP One AX
- AP One AX Lite
- AP Pro AX
- AP One Rugged HW2
- AP One AC Mini HW2
- AP One Flex HW4

## New Features

Reference	Description
<b>29827</b>	Support InTouch service on AP Series with valid Care Plan

## Improvements

Reference	Description
<b>30808</b>	Added support for remote updating of the captive-portal.peplink.com and device.pepwave.com SSL certificates
<b>30865</b>	Added the ability to disconnect Wi-Fi clients if their signal strength falls below a specified Client Signal Threshold
<b>30723</b>	Updated the SSL certificates for captive-portal.peplink.com and device.pepwave.com
<b>30318</b>	Added API support for getting mesh signal strength, connection status, and updating mesh settings
<b>27841</b>	Added option to disable 802.11ax support for specific SSID
<b>27776</b>	Added support for client type recognition on Web Admin
<b>28692</b>	Added support for GPIO and Ignition Sensing functionality on AP One Rugged
<b>27415</b>	Added support for performance test configuration in InControl2
<b>30640</b>	Added: Remote Assistance Duration Setting and Status - The Remote Assistance session will be turned off after the duration has expired. In addition, Remote Assistance will be turned off after this firmware upgrade, even if it was previously set to On
<b>30639</b>	Added: The Start/Stop of the Remote Assistance is now logged in the Event Log
<b>27126</b>	Default Configuration for 2.4GHz Radio now uses Auto Channel Selection (1, 6, 11) and 20MHz Channel Width
<b>28586</b>	Enhanced "Client Signal Threshold" feature for optimal AP roaming
<b>30641</b>	Enhanced the encryption for Diagnostic Report
<b>27445</b>	Fixed: WPA3 client could get disconnected from AP
<b>30066</b>	Improved stability of the Mesh connection
<b>30642</b>	Updated configuration file version. The configuration file for this firmware is not compatible with previous versions.

## Resolved Issues

Reference	Description
<b>29857</b>	Fixed issue where clients could not connect to the network after roaming to AP One Rugged HW2
<b>30518</b>	Fixed the issue where the Wireless Client > Details could show Disassociated for clients that successfully associated
<b>28473</b>	Fixed firmware upgrade failure issue
<b>29608</b>	Fixed issue where Mobile Wi-Fi clients would show "No Internet" when connecting to the SSID with VLAN
<b>30606</b>	Fixed: CVE-2022-47522 Wi-Fi Framing

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums: <https://forum.peplink.com/>