

## Firmware 8.3.1 Release Notes

Release Date: Apr 13, 2023

### **Devices Supported**

This firmware release supports the following devices:

- MAX BR1 Mini HW3
- MAX BR1 Mini Core HW3

#### **Important Notices**

- Firmware 8.3.1 is specifically designed for BR1 Mini / Mini Core HW3 only.
- The configuration file for Firmware 8.3.0 or later is not compatible with firmware versions 8.2.1 or earlier.
- **InControl** must be enabled on **PrimeCare** devices to update software features such as SpeedFusion (Bonding, WAN Smoothing, Hot Failover).



### **Improvements**

| Reference | Description   | Device Supported            |
|-----------|---|-----------------------------|
| 30148     | [BR1 Mini HW3] PrimeCare now includes all Feature Pack features (WAN Activation, Wi-Fi WAN, Hot Failover & WAN Smoothing) | MAX: BR1 Mini/Mini Core HW3 |

#### **Resolved Issues**

| Reference | Description   | Device Supported            |
|-----------|---|-----------------------------|
| 30021     | [BR1 Mini HW3] Resolved an issue where the device would alternate between a SIM reserved for management traffic and another SIM which was unable to connect | MAX: BR1 Mini/Mini Core HW3 |

#### **Known Issues**

| Reference | Description                            | Device Supported            |
|-----------|--|-----------------------------|
| 28109     | [System] YouTube blocking may not work | MAX: BR1 Mini/Mini Core HW3 |

# Report an Issue

To report an issue, please open a support ticket at: <a href="https://ticket.peplink.com/">https://ticket.peplink.com/</a>

For the latest development news and known issues, take a look at our forums: <a href="https://forum.peplink.com/">https://forum.peplink.com/</a>