

Peplink Switch Firmware 1.1.1 Release Notes

Release Date: 12/22/2017

New Features

Reference no.	Description
15113 17955	[LLDP] Added Support for LLDP TX reporting for Port ID, Port MAC, Port Desc and Port Capability and Port VLAN ID.
15347	[OOBM] Added USB modem support for Out of Band Management.
17212	[DHCP Snooping] Added DHCP Snooping: the ability to define trusted or untrusted ports to prevent unauthorized DHCP servers from offering IP addresses to DHCP clients.
17409	[STP] Added ability to configure STP bridge priority so that STP can decide which path is the best to the Root Bridge.
17109	[Usage Reports] Added hourly, daily, and monthly client usage statistics. This information is filterable by VLAN.

Feature Improvements

Reference no.	Description
17203	[Optimization] Optimized Connection to InControl and to Management VLAN.
17211	[Client Monitoring] Improved the ability to see the clients connected to the switch.
17713	[Web UI] The status page now shows switch and management port MAC addresses.
17715	[Web UI] Updated the Management Interface and introduce InControl Interface.

Resolved Issues

Reference no.	Description
17731	[Management VLAN] Unable to access the WebUI through switch's management VLAN IP under certain circumstances.
17965	[Remote Web Admin] Unable to upgrade firmware via Remote Web Admin on InControl. Attempting to do so causes the device to appear offline from InControl2 until the power is reset manually.
17050	[Wake-on-LAN] An error message appears when attempting to input a MAC address for the Wake-on-LAN feature.

Report a Bug

To report a bug, please open a forum thread at <https://forum.peplink.com/>