

# Peplink Switch Firmware 1.2.0 Release Notes

Release Date: Dec 13th, 2018

## Important Notice

**Feature Location Change:** The location of the OOBM function have been changed to “USB Modem Settings” on the Web UI. Please refer to the notes below under reference no.19145 for full details.

## New Features

Reference no.	Description
17931	<b>[Inter VLAN Routing]</b> Added Support for Inter VLAN Routing. The location of inter-VLAN routing is under Configure > Network Settings > LAN. Please note that the inter-vlan routing is enabled when inter-vlan address is saved.
19134	<b>[External Access]</b> Users can specify a static VLAN for external access.

## Feature Improvements

Reference no.	Description
19214	<b>[Management VLAN]</b> Added support for more than 1 management VLAN for Web Admin access.
17352	<b>[Web Admin]</b> The local Web Admin now shows Network Settings if the unit is managed by InControl.
19145	<b>[Web Admin - OOBM]</b> OOBM configuration has been renamed to “USB Modem Settings” and is now under System > Configuration.
19145	<b>[Web Admin - External Access]</b> External access settings have now have their own page under System > Configuration.

## Resolved Issues

Reference no.	Description
18341	<b>[DHCP]</b> When the VLAN network changes IP, the switch was unable to renew the IP.

## Report a Bug

To report a bug, please open a forum thread at <https://forum.peplink.com/>