

SD Switch Firmware 1.2.2 Release Notes

Release Date: May 7, 2020

Devices Supported

- SD Switch, 48-Port
- SD Switch, 24-Port
- SD Switch Rugged, 24-Port
- SD Switch Rugged, 16-Port
- SD Switch Rugged, 8-Port

New Features

Reference	Description
20799	[CLI] Added CLI support which allows reading system information, reboot, ping, traceroute, DNS lookup.
21993	[QoS] Added support for QoS Classification: - DSCP and 802.1p PCP support in QoS Classification. - Access Control > Ingress ACL supports DSCP Override and 802.1p PCP Override
22352	[Web UI] Added TACACS+ support for Web Admin Access
22543	[Security] The WebUI now enforces a password change after the first boot up, or when the default admin password is used.

Feature Improvements

Reference	Description
20653	[Web UI] Added a loading bar to the Client List when it is loading.
20774	[Routing] Added Static Route support for InterVLAN Routing
21116	[Web UI] Now, the Web UI always shows the device name on top-right as an identifier.
22163	[Port] Added support for Dynamic VLAN Assignment by Port-based 802.1X Authentication on the Access Port

Resolved Issues

Reference	Description
20978	[Web UI] Fixed an issue where Read Only Users are unable to access the Status > STP page
21549	[Web UI] Fixed an issue where the Client List may show invalid IP.
21570	[DHCP] Fixed an issue where DHCP requests used an outdated hostname.
21913	[Web UI] The 16-port SD Switch does not support link aggregation on its combo port (Port 16). Updated its WebUI to reflect this.
22082	[Web UI] Fixed an issue where the Dashboard may show the incorrect SFP/SFP+ port speed.
22105	[Web UI] Fixed an issue that causes the dashboard to show incorrect Link Aggregation Status information.
22221	[Port] Fixed an issue where Port-based 802.1X Authentication does not work on a Trunk Port
22499	[Port] Fixed an issue where the DSCP value will be set to zero when forwarding Ethernet frames.
22526	[Web UI] Fixed the known issue where the tooltip is missing on disabled checkboxes when using Safari browser in Firmware Beta 1

Report a Bug

To report a bug, please open a forum thread at <https://forum.peplink.com/>