

Smart Reader Firmware 1.1.2 Release Notes

Release Date: Nov 29, 2019

Devices Supported

- Smart Reader

Improvements

Reference	Description
16474	The minimum value of the Door Control timeout can now be set to 5 seconds. (Previous minimum was 10 seconds)
20008	Added an option to mute the buzzer.
20020	InControl 2 connection status is now visible on the display panel. Status can be seen on the icon on the top bar.
20088	If duplicate card credentials are detected, the TA system will provide the option to overwrite the card's credentials.

Resolved Issues

Reference	Description
19037	The Custom Message on panel may disappear in some situations
17436	Fixed an issue causing InControl 2 to show incorrect WAN status.

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/ticket/new/public>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>

