5G Dongle Firmware 2.0.3 Release Notes

Release Date: Mar 19, 2026

Devices Supported

- Pepwave 5G Dongle

Improvements

Reference	Description
35495	Added site survey support.

Resolved Issues

Reference	Description
35837	Fixed a RemoteSIM detection issue where the status could show No SIM Card Detected even when RemoteSIM was available.
35901	Fixed a Web UI issue where SIM-B might not appear in the SIM listing.
35870	Fixed a Web UI issue where the Client List could show Unauthorized for read-only users.
35414	Fixed an Admin Security issue where the Redirect HTTP to HTTPS setting in Web UI did not work correctly.
35147	Fixed an InTouch issue that could prevent remote management from working properly.
35846	Fixed an issue that could prevent eSIM installation through InControl.
35828	Fixed an issue where Carrier Selection was missing.
35951	Fixed an issue where the Data Roaming option was missing.

Report an Issue

To report an issue, please open a support ticket at:
https://ticket.peplink.com/

For the latest development news and known issues, take a look at our forums:
https://forum.peplink.com/