AP One Firmware 3.7.2 Release Notes

Release Date: Feb 12, 2020

Devices Supported

- AP One AC Mini HW2
- AP One Flex HW4

Improvements

Reference	Description
21843	Added LAN Port support for the AP One Flex HW4.

Resolved Issues

Reference	Description
22041	When managed by InControl 2, the "5GHz Auto" setting would not use correct channels.

Report an Issue

To report an issue, please open a support ticket at:
https://ticket.peplink.com/ticket/new/public

For the latest development news and known issues, take a look at our forums:
https://forum.peplink.com/