

AP Firmware 3.5.2 Release Notes

Release Date: 06/24/2015

Contents

1. Devices Supported
2. Important Notice
3. Obtaining the Firmware
4. New Features
5. Feature Improvements
6. Resolved Issues
7. Report a Bug

1. Devices Supported

This firmware release supports the following devices:

AP One:	AP One, mini, AC mini, 300M, In-Wall, Flex 300M
AP Pro:	AP Pro, 300M, Duo

2. Important Notices

SSL Certificate Expiring on Previous AP Firmware: Once the SSL certificate expires on August 13th, the captive portals of older Firmware will trigger browser warning messages. This can be prevented by upgrading your APs to Firmware 3.5.2.

Upgrade APs to 3.5.2 Before Upgrading to 6.2.1: When running Firmware 6.2.1, Peplink routers will be unable to upgrade APs running 3.5.0 or below using upgrade packs. If you are using a Peplink router to manage APs running 3.5.0 or below, please upgrade APs to Firmware 3.5.2 before upgrading your Peplink router.

Interface Overhaul: Firmware 3.5.2 has significant changes to its user interface, with several features moved to different locations. Please refer to the latest AP Firmware manual If you need to find out where a feature has been moved.

3. Obtaining the Firmware

AP Firmware 3.5.2 can be obtained here: <http://www.peplink.com/support/downloads/>

4. New Features

Feature	Description
Social Wi-Fi Hotspot with Facebook Logins	Use InControl 2 to configure and customize a captive portal per SSID. Guests can connect using Facebook, Open Access, Guest Accounts, or with a Token. * Active InControl 2 subscription is required.
Bandwidth Usage Quota Support	Pepwave Access Points now support usage quotas by bandwidth in addition to usage quotas by time.

5. Feature Improvement

Reference no.	Description
12850	SSID: For increased security, the default SSID has been changed from “open” to WPA2. The last 8 hex digits of the device’s LAN MAC address is the passphrase.

6. Resolved Issue

Reference no.	Description
12958	SSID: After an extended period of operation, client devices fail to associate to an SSID using WPA2 Enterprise authentication.

7. Report a Bug

To report a bug, please open a support ticket at <http://cs.peplink.com/contact/support/>.
For the latest development news, take a look at our forums: <https://forum.peplink.com/>.