



# PEPWAVE

## Mounting AP One In-Wall

### Package Contents





Metal Mount




AP One In-Wall


### You Have To Prepare



## 1 Connect the metal mount to socket box by screws



## 2 Hook the AP One In-Wall to the metal mount




# PEPWAVE Connecting the Cables

Connect an Ethernet cable providing PoE power and network connectivity to **either**

- the PoE In LAN 5/Uplink port using a standard RJ-45 connector, **or**
- the Punch-down block.

***Do not connect both.***

Using the PoE In LAN 5/Uplink port



Using the Punch-down block  
(Please follow the labelings below)

