

Peplink Balance 210/310/305/380/390/580/700/710/1350 Firmware 5.4.9

Firmware Upgrade Package

Release Notes

(May 23, 2013)



IMPORTANT NOTES - Please Read Carefully Before Upgrading.

- SpeedFusion Site-to-Site VPN 5.4 is backward compatible with Firmware 5.2/5.3
- For best performance, upgrade all VPN peers to the latest Firmware 5.4 release
- Firmware 5.4 now utilizes TCP port 32015 and UDP port 4500 (Firmware 5.2/5.3 utilized TCP port 32015 and UDP port 32015)

Changes to Firmware 5.4.9 since 5.4.7

Added:

- Lowest latency mode for SpeedFusion
- Manual mapping for SpeedFusion support

Improved:

- Overall system stability
- SpeedFusion stability and performance
- Local DNS proxy stability and performance
- Client bandwidth usage display issue