

Installation Guide

Please follow the assembling instructions for


the kits relevant to your devices.

DC Power Connector (Soldering type)

In the Kit









Side view



You have to prepare


DC Power





DC Power Connector (Solderless type I)

In the Kit a b Pin 1 Pin 3








You have to prepare

DC Power





DC Power Connector (Solderless type II)

In the Kit



Front view





You have to prepare


Side view





AC Power Connector (Soldering type)

In the Kit






You have to prepare

AC Power









AC Power Connector (Solderless type)


In the Kit














You have to prepare

AC Power





Metal Ethernet Connector

In the Kit





C






e





You have to prepare


Ethernet Cable











Plastic Ethernet Connector

In the Kit









You have to prepare

Ethernet Cable









Fiber Connector

In the Kit



c

You have to prepare

Fiber Cable



