

AP One Firmware 3.6.2 Release Notes

Release Date: Nov 27, 2020

Devices Supported

- AP One Rugged
- AP One Enterprise
- AP One AC Mini HW1
- AP One Flex HW2,3
- AP Pro AC

New Features

Reference	Description
23242	Added WDS support. (Not compatible with firmware 3.5.x or below)
23338	Added support for Wi-Fi Mesh.
23388	Added support for WPA3 security policy.
23491	Added ability to change from "AP Mode" to "Wi-Fi Air Monitoring mode" under "System > Operation Mode" , and the report can be viewed from InControl 2 > Reports > AirProbe Reports.

Improvements

Reference	Description
23382	Decreased the number of redirections to the Captive Portal splash page.

Resolved Issues

Reference	Description
18160	Fixed the issue where the setting for "Maximum Number of Clients" in "AP > Settings" was not working.
21393	Fixed the issue of Multicast Filter not working.
21987	Fixed the issue of Dynamic VLAN not working.
22582	Fixed the issue of the Event Log missing from Remote Web Admin access.
23269	Fixed the issue where using Channel 149 while the region was set to "US" resulted in lower transmit power.

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>