

AP One Firmware 3.8.1 Release Notes

Release Date: Nov 27, 2020

Devices Supported

- AP One AX

New Features

Reference	Description
23820	Added ability to view the DPI report via InControl.
23821	Added ability to change from "AP Mode" to "Wi-Fi Air Monitoring mode", and the report can be viewed from InControl 2 > Reports > AirProbe Reports.
23822	Added WDS support. (Not compatible with firmware 3.5.x or below)
23363	Added support for Wi-Fi Mesh.

Improvements

Reference	Description
23505	Added LED control (On/Off) support for AP One AX.

Resolved Issues

Reference	Description
23404	Fixed a driver issue that sets lower Tx power than it should be based on the regulatory domain.
23167	Fixed a MAC address conflict issue caused by using WPA2 Enterprise with Dynamic VLAN.
23336	Fixed 802.11k Fast Roaming related issues.

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>