

Firmware 3.9.0 Release Notes

Release Date: May 18, 2021

Devices Supported

- AP One AX
- AP One AC Mini HW2
- AP One Flex HW4

Improvements

Reference	Description
23908	Added description on WAN/LAN page in Bridge mode
24839	Added LED indicator to show "Connecting/Connected" status for Wi-Fi Mesh Uplink
23695	Added support for WPA3 Enhanced Open Security Mode
24828	Improved the speed at which Wi-Fi Mesh connections are established
24632	The Wireless Clients List now shows WPA, WPA2, and WPA3
24192	Updated device SSL certificate

Resolved Issues

Reference	Description
22652	Fixed the issue causing Wi-Fi clients to not connect to 2.4 GHz SSID on the AP One AC Mini HW2 and on the AP One Flex HW4

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>