

Device Connector Firmware 1.2.1 Release Notes

Release Date: Feb 9, 2023

Devices Supported

This firmware release supports the following devices:

- Device Connector Rugged
- Device Connector IP55 HW2-3
- Device Connector IP55 HW4



Improvements

Reference	Description
22971	[System] Removed CLI Support
22961	[Web UI] "Device Name" is used instead of "Router Name" in Status and System page
28891	[Wi-Fi WAN] Added: OWE security policy on Wi-Fi WAN

Resolved Issues

Reference	Description
29030	[AP] Fixed: Bandwidth Management under SSID settings did not work
28554	[DCS IP55 HW4] Fixed: LAN PoE did not work
23589	[System] Fixed: Unable to access Web Admin if the device was configured LAN Only access in bridge mode
28826	[Wi-Fi WAN] Fixed: Wi-Fi WAN could not connect to the AP with EAP-TLS or EAP TTLS

Report an Issue

To report an issue, please open a support ticket at: https://ticket.peplink.com/

For the latest development news and known issues, take a look at our forums: https://forum.peplink.com/