

Router Firmware 8.3.2 Release Notes

Release Date: August 21, 2026

Devices Supported

This firmware release supports the following devices:

Balance	20 HW7-8 / 210 HW2-3 / 30 LTE HW1-2 / 310 HW2-3 /50 HW1-3
MAX	700 HW1-2 / BR1 HW2-3 / BR1 HW1 / BR1 ESN HW1 / BR1 IP55 HW1-3 / BR1 IP67 HW1 / BR1 M2M HW1-3 / BR1 MK2 HW1-3 / BR1 Mini HW1-2 / BR1 Mini Core HW1-2 / BR1 Pro HW2-6 / BR1 Slim HW1 / BR2 HW2-3 / BR2 IP55 HW2-3 / HD2 HW1-4 / HD2 IP67 HW1 / Hotspot HW1 / On-The-Go HW2 / Transit Mini HW1
SpeedFusion Engine	SpeedFusion Engine HW1-2
Surf	SOHO HW2 / SOHO MK3 HW1
UBR	LTE HW1-2

Resolved Issues

Reference	Description
37208	[Security Advisory] Fixed a SSH CLI vulnerability that could allow command injection.
37210	[Security Advisory] Fixed a vulnerability that could allow read-only users to access secrets (CVE-2023-49230).
32010	[Security Advisory] Fixed an OS command injection vulnerability (CVE-2023-49226).
37203	[Security Advisory] Fixed console port access that could grant root privileges (CVE-2023-49228).
37207	[Security Advisory] Fixed missing authorization controls on captive portals (CVE-2023-49229).
37202	[Security Advisory] Fixed a vulnerability in the API that could allow remote code execution
37317	[Security Advisory] Updated SSH CLI components to address multiple security vulnerabilities.
37350	[Security Advisory] Updated web service components to address CVE-2026-42945.

Report an Issue

To report an issue, please open a support ticket at: For the latest development news and known issues, take a look at our forums: