

FusionHub Firmware 7.1.0 Release Notes

Release Date: Feb. 23, 2018

Feature Improvements

Reference	Feature
14507	[PepVPN] The PepVPN Receive Buffer now enables users to configure a buffering time for received packets, which helps to reduce jitter and out of order packets.
11611	[PepVPN] The PepVPN Status page now provides more information when link failure happens; helping to identify whether it failed to send, or failed to receive.
17085	[PepVPN Test] The test has been enhanced to provide granular WAN-to-WAN control and statistics.
16231	[PepVPN] WAN-to-WAN connection statistics do not appear when using the PepVPN "Weighted Round Robin" mode.

Report a Bug

To report a bug, please open a support ticket at <https://contact.peplink.com/secure/create-support-ticket.html>.

For the latest development news, and known issues, take a look at our forums: <https://forum.peplink.com/>