

# SD Switch Firmware 1.2.3 Release Notes

Release Date: Jul 13, 2020

## Devices Supported

- SD Switch, 48-Port
- SD Switch, 24-Port
- SD Switch Rugged, 24-Port
- SD Switch Rugged, 16-Port
- SD Switch Rugged, 8-Port

## Feature Improvements

Reference	Description
<b>22966</b>	<b>[CLI]</b> "Device Name" is used instead of "Switch Name"
<b>22963</b>	<b>[Web UI]</b> "Device Name" is used instead of "Switch Name" in Status and System page

## Resolved Issues

Reference	Description
<b>23018</b>	<b>[Client List]</b> Fixed an issue where the Client IP on Client List does not update if the client has moved to another port
<b>23015</b>	<b>[Client List]</b> Fixed an issue where the Client List cannot show the Client IP on link aggregation ports
<b>22692</b>	<b>[Client List]</b> Reduced unnecessary ARP ping requests during client probe
<b>23088</b>	<b>[External Access]</b> Fixed an issue of External Access may cause system instability
<b>22741</b>	<b>[External Access]</b> Fixed an issue where DNS requests will only route via Default Gateway, even the custom local LAN DNS server is configured
<b>22698</b>	<b>[InControl 2]</b> Device will not send health check packets to InControl 2 when External Access is Custom and USB Modem is disabled
<b>22949</b>	<b>[System]</b> Fix for the CVE-2018-1000517 vulnerability
<b>22948</b>	<b>[System]</b> Fix for the CVE-2019-5747 vulnerability

## Report a Bug

To report a bug, please open a forum thread at <https://forum.peplink.com/>