

SD Switch Firmware 1.3.1 Release Notes

Release Date: Jul 27, 2023

Devices Supported

This firmware release supports the following devices:

- SD Switch 48-Port Enterprise HW1
- SD Switch 24-Port Enterprise HW1-3
- SD Switch 24-Port Rugged HW1-2
- SD Switch 16-Port Rugged HW1-2
- SD Switch 8-Port Rugged HW1-2

New Features

Reference	Description
24995	Added IGMP Fast Leave support
29778	Added support for InTouch service on SD Switch with valid Care Plan

Improvements

Reference	Description
29787	Added: Remote Assistance Duration Setting and Status - The Remote Assistance session will be turned off after the duration has expired. In addition, Remote Assistance will be turned off after this firmware upgrade, even if it was previously set to On. Added: The Start/Stop of the Remote Assistance is now logged in the Event Log
29772	Improved encryption for Diagnostic Report

Resolved Issues

Reference	Description
26587	Fixed an issue that could cause system instability due to a large client list.
28861	Fixed an issue where port status could not be displayed due to unexpected EEPROM content on SFP transceivers.
25899	Fixed an issue where the switch could become unstable after booting with a subnet mask less than 24 bits
28872	Fixed the SNMP memory usage issue that could cause unexpected reboots

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>