

Firmware 3.5.1 Release Notes

Release Date: Mar 11, 2015

Contents

1. Devices Supported	1
2. New Features	2
3. Feature Improvements	2
4. Resolved Issues	3
5. Report a Bug	3

1. Devices Supported

This firmware release supports the following devices:

Pepwave AP		
AP One	AP One 300M	AP One Flex
AP One In-Wall	AP One AC mini	AP One mini
AP Pro	AP Pro Duo	

2. New Features

Feature	Description
Multi-language support	The Web Admin Interface supports Traditional and Simplified Chinese.

3. Feature Improvements

Reference no.	Improvement
10796	Captive Portal supports JSONP responses on login / logout.
12153	Enhanced Wi-Fi stability
10792	Improved Web Admin Interface layout
11897	More secure HTTPS Certificate.
11745	During firmware upgrade, the <i>Status</i> LED will flash instead of turned off

4. Resolved Issues

Reference no.	Symptom
12019	Glitches in InControl 2 on data and status reporting
11506	Incorrect 5G power level.
10901	Glitches in AP Controller on data reporting & controls
11382	Band steering
11722	Vulnerability - the POODLE Attack (CVE-2014-3566)
11511	PPPoE does not support special characters.
12191	WDS malfunction on AP One AC mini

5. Report a Bug

To report a bug, please open a support ticket at <http://cs.peplink.com/contact/support/>.
For the latest development news, take a look at our forums: <https://forum.peplink.com/>.