

# FusionHub Release 7.0.1 Release Notes

Release Date: 06/07/2016

## 1. Important Notices

**DPI Reporting to InControl is disabled by default:** After upgrading to Firmware 7, DPI reporting will be disabled by default. If you require DPI Reporting, please enable it from InControl.

## 2. New Features

Reference no.	Improvement
14960	<b>Static Routes:</b> Added Support custom static routes
15076	<b>System Tools:</b> Added ping and traceroute tools

## 3. Feature Improvements

Reference no.	Improvement
9510	<b>Event Log:</b> Added web admin login history to event log
15673	<b>VPN:</b> Redesigned IPsec implementation. NAT Traversal is always enabled.
16315	<b>InControl DPI Support:</b> DPI reporting can be switched on/off via InControl

## 4. Resolved Issues

Reference no.	Improvement
15486	<b>IPsec:</b> IPsec algorithm SHA-256 is not functional.
16198	<b>PepVPN:</b> Unexpected reboot issue when the device receives network packets with specific patterns for a period of time. Networks with Microsoft Exchange DAG running across PepVPN are known to be affected.

## 5. Report a Bug

To report a bug, please open a forum thread at <https://forum.peplink.com/>