

AirProbe Firmware 1.0.1 Release Notes

Release Date: Feb 7th 2018

Contents

1. Obtaining the Firmware
2. New Features
3. Feature Improvements
4. Report a Bug

1. Obtaining the Firmware

AirProbe Firmware 1.0.1 can be obtained here: <https://www.peplink.com/open-beta-program/>

2. New Features

Reference	Feature
16290 17066	[Wired Interfaces] The AirProbe can now discover devices and perform packet capture on wired networks.
16969	[Performance Test] Added ability to conduct performance tests on Ethernet interfaces.
16970	[Port Scan] Added support for port scanning for IP addresses and domain names. Useful for checking firewall settings and to identify open ports and services on a network host.
16287	[Traceroute Test] Added support for Traceroute tests. Useful for checking how the traffic reaches the destination via the target SSID.

3. Feature Improvements

Reference	Feature
17851	[Air Monitor] The Air Monitor report now shows the channel width of detected access points.
16287	[Performance Test] When performing testing, users can now input a custom MAC address to hide the actual identity.
16405	[Heatmap] Click on any point on the hourly heat map to show corresponding info for that minute.
16622	[WPA/WPA 2 Enterprise] The AirProbe can now perform tests on networks with WPA/WPA2 Enterprise, and 802.1x SSID

4. Report a Bug

To report a bug, please open a support ticket at <https://contact.peplink.com/secure/create-support-ticket.html>.

For the latest development news, and known issues, take a look at our forums: <https://forum.peplink.com/>