

Router Firmware 8.5.5 Release Notes

Release Date: August 21, 2026

Devices Supported

This firmware release supports the following devices:

Balance	30 LTE HW / 30 Pro HW1 / 210 HW4-5 / 310 HW4 / One HW1-3 / One Core HW1
MAX	700 HW3-4 / BR1 ENT HW1-2 / HD1 Dome HW1 / HD2 HW5-6 / HD2 Dome HW1 / HD2 IP67 HW2-5 / HD2 Mini HW1-4 / HD2 with MediaFast HW1-4 / HD4 HW1-5 / HD4 IP67 HW1 / HD4 with MediaFast HW1-4 / Transit HW1-3 / Transit 5G HW2-3 / Transit Core HW1 / Transit Duo HW1-3 / Transit Duo Pro E HW1 / Transit Pro E HW1
MediaFast	200 HW1 / HW3
SpeedFusion Engine	SFE CAM HW1

Resolved Issues

Reference	Description
37226	[Security Advisory] Fixed a SSH CLI vulnerability that could allow command injection.
37227	[Security Advisory] Fixed a Web Admin vulnerability that could allow unauthenticated access to internal binaries.
37225	[Security Advisory] Updated SSH CLI components to address multiple security vulnerabilities.
37247	[Security Advisory] Updated web service components to address CVE-2026-42945.

Report an Issue

To report an issue, please open a support ticket at: [For the latest development news and known issues, take a look at our forums:](#)