

# SD-Switch Firmware 1.2.1 RC1 Release Notes

Release Date: Jun 11th, 2019

## Devices Supported

- SD Switch 48-Port
- SD Switch 24-Port
- SD Switch 8-Port Rugged

## Changes Since 1.2.1 Beta 1

Reference	Description
20922	<b>[Web UI]</b> A message box saying "Invalid rule order" may appear in "Access Control > Ingress ACL".

## New Features

Reference	Description
20372	<b>[802.1X]</b> Added support for Port-based 802.1X Authentication.
20370	<b>[IGMP Snooping]</b> Added support for IGMP Snooping.

## Feature Improvements

Reference	Description
20541	<b>[Web UI]</b> Added physical connection status for external access.
20105	<b>[Web UI]</b> Dashboard shows Port Mode and VLAN Information.
20585	<b>[Web UI]</b> STP Status shown on Status page.
20657	<b>[Web UI]</b> Added the ability to select Speed and Duplex on a Combo Port.
20820	<b>[InControl]</b> Added an option to restrict InControl push configuration.

## Resolved Issues

Reference	Description
<b>20627</b>	<b>[Port Mirroring]</b> Fixed the ingress/egress traffic direction.
<b>20439</b>	<b>[Client List]</b> Fixed the issue of devices being on the Client List even if they are offline.

## Report a Bug

To report a bug, please open a forum thread at <https://forum.peplink.com/>